




SUPREMA® Kombi



120/80/6	= 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m²	1 vrstva (kombiforma) = 0,96 m ²




Vzor 1	Prodej na vrstvy: 1 vrstva (kombiforma) = 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m²	1 vrstva (kombiforma) = 0,96 m ²




Vzor 2	Prodej na vrstvy: 1 vrstva (kombiforma) = 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m²	1 vrstva (kombiforma) = 0,96 m ²


SUPREMA® Kombi




Vzor 3	Prodej na vrstvy: 1 vrstva (kombifforma)
	= 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²



Vzor 4	Prodej na vrstvy: 1 vrstva (kombifforma)
	= 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²





Vzor 5	Prodej na vrstvy: 1 vrstva (kombifforma)
	= 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²




Vzor 6	Prodej na vrstvy: 1 vrstva (kombifforma)
	= 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²

SUPREMA® Kombi



Vzor 7	Prodej na vrstvy: 1 vrstva (kombifforma)
	= 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²

Vzor 8	Prodej na vrstvy: 1 vrstva (kombifforma)
	= 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²



Vzor 9	Prodej na vrstvy: 1 vrstva (kombifforma)
	= 2 ks 60/40/6 + 1 ks 40/20/6 + 2 ks 40/40/6 + 2 ks 20/20/6
Spotřeba ks/m ²	1 vrstva (kombifforma) = 0,96 m ²